



**Oil Trap & Crankcase Ventilation**

**Model Type Year Oe Ref Art No**



**Bushing Inlet Manifold**

900,9000	Bushing inlet manifold		7515208	<b>61345208</b>	
----------	------------------------	--	---------	-----------------	---



**Bushing Nipple for Vacuum Hose**

900, 9000, 9-3, 9-5	Petrol 4 cyl Petrol 4 cyl Petrol 4 cyl Petrol 4 cyl	-2003	7515190 (9549593)	<b>23349593</b>	
------------------------------	--	-------	----------------------	-----------------	---

**Valves**





900,9000 9-3,9-5	Vacuum valve	1986-98 1998-03	7521313 (9189564)	<b>21341313</b>	
9-5	Vacuum valve B205, B235	1998-10	55558115	<b>21348115</b>	

**Crank Ventilation Nipple**

900  9000	B201 Turbo B202 B202,B212  Turbo B202 B234	1987-89 1986-89 1990-94 1985 1988 1990-91 1990-93	7517048	<b>23347048</b>	
900 9-3	4 cyl 4 cyl petrol	1994-98 1998-00	30551957	<b>23341957</b>	

<b>By-Pass Valve / Overrun Cut-Off Valve</b>					
<b>Model</b>	<b>Type</b>	<b>Year</b>	<b>Oe Ref</b>	<b>Art No</b>	
900	B202 & B212 Also fits earlier 900 16v models to fix the "no heat at idle" problem. Necessary is to use additional hoses that accompanies the by-pass valve to complete modification.	1990-93	4073706	<b>87343706</b>	
900 9000 9-3 9-5	Turbo Turbo Turbo Turbo	-1998 1998-03 1998-10	4391157	<b>21341157</b>	
<b>Flame Trap Nipple</b>					
9-3 9-5	B205, B235 B205, B235	1999-03 1999-03	55560443 (9192949) (30588567)	<b>21340443</b>	
<b>Oil Trap</b>					
9-5	B205, B235	2004-05	55558696 (5961628) (9549213)	<b>21341628</b>	
9-5	B205, B235	2006-10	12755243	<b>21345243</b>	
<b>Oil Fill Pipe</b>					
9-3 9-5	B205, B235 B205, B235	2000-02 1998-10	55561216	<b>21341216</b>	

<b>Crankcase Ventilation Hose</b>					
<b>Model</b>	<b>Type</b>	<b>Year</b>	<b>Oe Ref</b>	<b>Art No</b>	
9-3	Pipe. B284	2006-11	12588557	<b>21348557</b>	
9-3 9-5	B205, B235 B205, B235	1998-03 1998-03	55560462	<b>23340462</b>	
9-3 9-5	B205, B235 B205, B235	1998-03 1998-03	9399973	<b>23349973</b>	
9-3	B205, B235	1999-03	55560463	<b>23340463</b>	
9-5	B205, B235	2005-10	55560445	<b>23340445</b>	
9-5	B205, B235	2004-10	5955927	<b>21345927</b>	
9-5	B205, B235 Heavy duty performance crankcase check valve	2004-10	5955927	<b>21345927HD</b>	
9-5	B205, B235 Eng -4017590	2004-	5961552	<b>21341552</b>	
9-5	B205, B235 Eng 4017591-	2004-	5961610	<b>21341610</b>	
9-5	B205, B235	2006-10	55355330	<b>21345330</b>	
9-5	B205, B235	2006-10	55557709 (9549528)	<b>21349528</b>	

<b>Crankcase Ventilation Kit</b>					
<b>Model</b>	<b>Type</b>	<b>Year</b>	<b>Oe Ref</b>	<b>Art No</b>	
9-3 9-5	Crankcase ventilation upgrade complete kit 4 cyl B205 & B235  Kit includes: 21341200 Crankcase ventilation upgrade 23340445 Crankcase hose 23349973 Crankcase hose 23340463 Crankcase hose	2000-02 1998-03	55561200	21341200C	
9-3 9-5	Crankcase ventilation upgrade 4 cyl B205 & B235 Crankcase ventilation upgrade to prevent damages on your engine.	2000-02 1998-03	55561200	21341200	
9-5	Crankcase ventilation kit 4 cyl B205 & B235	2004-10		21345243C	
 <p> <b>21341610</b>  <b>21341552</b>  <b>21345330</b>  <b>21341628</b>  <b>21345243</b>  <b>21349528</b>  <b>23340445</b>  <b>21340443</b>  <b>23340463</b>  <b>23341957</b>  <b>23349973</b>  <b>23340462</b> </p>					